

Changes For HBLT Version 2.42

Author: Charles E. Southward

Date: December 7, 2005

Revised: December 7, 2005

This version makes the following changes:

1. Corrected all known programming errors.
2. Changed the safety door opened action to cancel the running test or script and display a message. If using Pressure Manager, Pressure Manager displays the error.
3. All volume delivery and volume reporting functions are now active for positive pressures only.