

Changes For HBLT Version 1.62

Author: Charles E. Southward

Date: September 19, 1997

Revised: September 19, 1997

This version makes the following changes:

1. Added additional intake limit checks and exhaust limit checks during run test mode. Certain customer tests with compliant products caused motor stall errors.