

## **Customer Changes in *HBLT* application from version 2.20 to version 2.21**

Author: Charles E. Southward

Date: November 22, 2004

This version makes the following changes:

1. Corrected the Smart Manifold sequential mode to not require the operator to press the Start button.
2. Corrected the Smart Manifold results summary screen to display the correct number of cycles when running a group test that results in no error conditions.
3. Corrected the group test vacuum piston positioning.